

United States Patent and Trademark Office

UNITED STATES DEPARTMENT OF COMMERCE United States Patent and Trademark Office Address: COMMISSIONER FOR PATENTS P.O. Box 1450 Alexandria, Virginia 22313-1450 www.uspto.gov

| APPLICATION NO. | FILING DATE | FIRST NAMED INVENTOR | ATTORNEY DOCKET NO. | CONFIRMATION NO |
|---|----------------|----------------------|-------------------------|-----------------|
| 10/708,571 | 03/11/2004 | Peng Lee | 026018.50271 | 2570 |
| 28172 7 | 590 06/08/2006 | | EXAMINER | |
| BUTLER, SNOW, O'MARA, STEVENS & CANNADA PLLC 6075 POPLAR AVENUE SUITE 500 | | | JAGAN, MIRELLYS | |
| | | | ART UNIT | PAPER NUMBER |
| MEMPHIS, TN 38119 | | | 2859 | |
| | | | DATE MAILED: 06/08/2006 | 5 |

Please find below and/or attached an Office communication concerning this application or proceeding.

| U.S. Pa | stent and | t Trad | emark | Office |
|---------|-----------|----------|-------|------------|
| 570 | | / | | ~ \ |

1) Notice of References Cited (PTO-892)

Paper No(s)/Mail Date _____.

2) Notice of Draftsperson's Patent Drawing Review (PTO-948)

Information Disclosure Statement(s) (PTO-1449 or PTO/SB/08)

6) Other: ____.

4) Interview Summary (PTO-413)

Paper No(s)/Mail Date. _____.

5) Notice of Informal Patent Application (PTO-152)

DETAILED ACTION

Drawings

1. Color photographs and color drawings are not accepted unless a petition filed under 37 CFR 1.84(a)(2) is granted. Any such petition must be accompanied by the appropriate fee set forth in 37 CFR 1.17(h), three sets of color drawings or color photographs, as appropriate, and, unless already present, an amendment to include the following language as the first paragraph of the brief description of the drawings section of the specification:

The patent or application file contains at least one drawing executed in color. Copies of this patent or patent application publication with color drawing(s) will be provided by the Office upon request and payment of the necessary fee.

Color photographs will be accepted if the conditions for accepting color drawings and black and white photographs have been satisfied. See 37 CFR 1.84(b)(2).

Claim Rejections - 35 USC § 103

- 2. The following is a quotation of 35 U.S.C. 103(a) which forms the basis for all obviousness rejections set forth in this Office action:
 - (a) A patent may not be obtained though the invention is not identically disclosed or described as set forth in section 102 of this title, if the differences between the subject matter sought to be patented and the prior art are such that the subject matter as a whole would have been obvious at the time the invention was made to a person having ordinary skill in the art to which said subject matter pertains. Patentability shall not be negatived by the manner in which the invention was made.
- 3. This application currently names joint inventors. In considering patentability of the claims under 35 U.S.C. 103(a), the examiner presumes that the subject matter of the various claims was commonly owned at the time any inventions covered therein were made absent any evidence to the contrary. Applicant is advised of the obligation under 37 CFR 1.56 to point out

Art Unit: 2859

the inventor and invention dates of each claim that was not commonly owned at the time a later invention was made in order for the examiner to consider the applicability of 35 U.S.C. 103(c) and potential 35 U.S.C. 102(e), (f) or (g) prior art under 35 U.S.C. 103(a).

4. Claim 10 is rejected under 35 U.S.C. 103(a) as being unpatentable over the ASTM-C1060-90 standard titled "Standard Practice for Thermographic Inspection of Insulation Installations in Envelope Cavities of Frame Buildings" in view of the publication titled "100's of Tips on Saving Energy and Money at Home" (www.mississauga4sale.com/newsletter/energy_saving_tips.htm) by Argentino.

Referring to claim 10, ASTM-C1060-90 discloses a method of inspecting building components, the method comprising:

creating a temperature differential of greater than 10°F between the inside and the outside of the building and maintaining it for a period of time (at least 4 hrs);

obtaining temperature profiles of an exterior building wall;

obtaining temperature profiles of the interior of a pitched roof (attic);

obtaining temperature profiles of interior building components;

assessing each profile to detect a thermal anomaly (air leakage/poor insulation) indicative of a problem with the building components; and

reporting the thermal anomaly indicative of a problem to a designated entity (see sections 1.4; 4.1; 5.1; 9.23; 9.41; 10.24; 10.241; 10.2.4.4; X2.2; and X2.4).

ASTM-C1060-90 does not disclose the particular interior building components, obtaining temperature profiles of each electrical circuit in the building, and turning on substantially all light switches and exhaust blowers in the building.

Application/Control Number: 10/708,571

Art Unit: 2859

Argentino discloses that energy audits are conducted in a residential building by using an infrared camera to inspect the interior building components for poor energy efficiency. An infrared camera obtains thermal images (temperature profiles) of the detected building components, and will show the presence of air infiltration or poor thermal insulation of the building. The interior building components that should be inspected include the building's electric wires and box, all ducts, and electrical outlets and switches because these are all sources of air infiltration or poor thermal insulation of the building that will affect the energy efficiency of the building (see "Insulation" on pages 2-3; "sources of Air Leaks in Your Home" on pages 3-4; and Ducts" on pages 7-8).

It would have been obvious to one having ordinary skill in the art at the time the invention was made to modify the method of ASTM-C1060-90 by obtaining temperature profiles of all of the electrical circuits and ducts when inspecting the interior components of the building, since Argentino teaches that these are sources of air infiltration that will affect the energy efficiency of the building

Furthermore, it would have been obvious to one having ordinary skill in the art at the time the invention was made to modify the method of ASTM-C1060-90 and Argentino by turning on substantially all light switches when testing the electric circuits and turning on substantially all exhaust blowers when testing the ducts in order to determine the location of any thermal anomaly, i.e. the current in the electrical circuits must be active to determine the thermal anomaly in the circuits, and air must be flowing through the ducts in order to determine if there is a thermal anomaly in the ducts.

Art Unit: 2859

5. Claims 26-30 are rejected under 35 U.S.C. 103(a) as being unpatentable over ASTM-C1060-90 in view of Argentino and the publication titled "Infrared Inspection: Sample Home Inspection" by Boldstar.

ASTM-C1060-90 discloses a method of inspecting interior building components, the method comprising:

obtaining temperature profiles of interior building components;

assessing each profile to detect an anomaly (air leakage/poor insulation) indicative of a problem.

ASTM-C1060-90 does not disclose the interior building components including all of the electrical outlets, and assessing their profiles for an anomaly indicating an electrical problem, and turning on substantially all light switches and exhaust blowers in the building.

Argentino discloses that energy audits are conducted in a residential building by using an infrared camera to inspect the interior building components for poor energy efficiency. An infrared camera obtains thermal images (temperature profiles) of the detected building components, and will show the presence of air infiltration or poor thermal insulation of the building. The interior building components that should be inspected include the building's electric wires and box, all ducts, and electrical outlets and switches because these are all sources of air infiltration or poor thermal insulation of the building that will affect the energy efficiency of the building (see "Insulation" on pages 2-3; "sources of Air Leaks in Your Home" on pages 3-4; and Ducts" on pages 7-8).

Boldstar discloses a method of inspecting interior building components that includes obtaining temperature profiles of electrical circuits in the building (electrical panel), and

Art Unit: 2859

assessing the thermal profiles for an anomaly indicative of an electrical problem such as overheating, circuit overload, or connection overheating (i.e., hot wire), wherein the profiles are recorded on a digital recording device (see images).

Referring to claim 26, it would have been obvious to one having ordinary skill in the art at the time the invention was made to modify the method of ASTM-C1060-90 by obtaining temperature profiles of all of the electrical outlets and ducts when inspecting the interior components of the building, since Argentino teaches that these are sources of air infiltration that will affect the energy efficiency of the building. Furthermore, it would have been obvious to one having ordinary skill in the art at the time the invention was made to modify the method of ASTM-C1060-90 and Argentino by further assessing the profiles of the electrical outlets for an anomaly indicating an electrical problem, as taught by Boldstar, in order to determine if the circuits are overheating.

Accordingly, it would have been obvious to one having ordinary skill in the art at the time the invention was made to modify the method of ASTM-C1060-90, Argentino, and Boldstar above by turning on substantially all light switches when testing the electric circuits and turning on substantially all exhaust blowers when testing the ducts in order to determine the location of any thermal anomaly, i.e. the current in the electrical circuits must be active in order to determine a thermal anomaly in the circuits, and air must be flowing through the ducts in order to determine if there is a thermal anomaly in the ducts.

Response to Arguments

6. The declarations under 37 CFR 1.132 filed 4/17/06 are insufficient to overcome the rejection of claims 10, 26-30, and 60-62 based upon the prior art of record as set forth in the last Office action because it include(s) statements which amount to an affirmation that the affiant has never seen the claimed subject matter before. This is not relevant to the issue of nonobviousness of the claimed subject matter and provides no objective evidence thereof. See MPEP § 716.

Furthermore, it states that the claimed subject matter solved a problem that was long standing in the art. However, there is no showing that others of ordinary skill in the art were working on the problem and if so, for how long. In addition, there is no evidence that if persons skilled in the art who were presumably working on the problem knew of the teachings of the above cited references, they would still be unable to solve the problem. See MPEP § 716.04.

In view of the foregoing, when all of the evidence is considered, the totality of the rebuttal evidence of nonobviousness fails to outweigh the evidence of obviousness.

7. Applicant's arguments that the Examiner has failed to establish a prima facie case of obviousness because the cited art fails to disclose the element of "turning on substantially all light switches and substantially all exhaust blowers in said residential building", as claimed in claims 10 and 26, are not persuasive because, to establish a prima facie case of obviousness, there must be some suggestion or motivation, either in the references themselves or in the knowledge generally available to one of ordinary skill in the art, to modify the reference or to combine reference teachings.

Application/Control Number: 10/708,571

Art Unit: 2859

In this case, the cited prior art teaches obtaining temperature profiles of all of the electrical outlets and ducts when inspecting the interior components of the building, and assessing the profiles of the electrical outlets and ducts for an anomaly indicating an electrical problem to determine if the circuits are overheating and to determine if the ducts are leaking, respectively; wherein turning on substantially all light switches and substantially all exhaust blowers in the building ducts when doing such tests is within the knowledge that is generally available to one of ordinary skill in the art since it must be performed in order to inspect the electrical outlets and ducts without having to move from area to area turning each outlet and duct on, i.e., saves time to turn them all on at once and inspect them while they are all on.

Conclusion

8. Any inquiry concerning this communication or earlier communications from the examiner should be directed to Mirellys Jagan whose telephone number is 571-272-2247. The examiner can normally be reached on Monday-Friday from 11AM to 5PM.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Diego Gutierrez can be reached on 571-272-2245. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

Application/Control Number: 10/708,571 Page 9

Art Unit: 2859

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free).

MJ

June 1, 2006

Mirellys Jagan
Patent Examiner

Technology Center 2800